

< Konica Minolta Confidential >

TAD(Technical Advice Database)

Please be noticed that this information was originally issued for a specific market only and may not be applicable to your market.

[ID No.] TAUS0800338EN01

Publisher

[Company] BUS

[Group] BUS_Service_Production

Contents

[Original Doc. No.] TAUS0800338EN00

[Open Date] 31.03.2009

[Doc. Language] English

[Doc. Priority]

[Product Name] bizhub C200
bizhub C203
bizhub C250
bizhub C250P
bizhub C252
bizhub C252P
bizhub C253
bizhub C300
bizhub C351
bizhub C352
bizhub C352P
bizhub C353
bizhub C353P
bizhub C450
bizhub C450P
bizhub C451
bizhub C452
bizhub C550
bizhub C552
bizhub C650
bizhub C652
bizhub PRO C5500
bizhub PRO C5501
bizhub PRO C6500

[Option]

[Subject] What port and protocol is used for the driver auto configuration feature?

[Description]

What port and protocol is used for the driver auto configuration feature?

[Solution]

The port number used for the driver auto configuration option is Port 161 and the protocol is SNMP.

SPECIAL NOTE: Solution contribution by Mark D'Attilio and Ian Lynch, Production Print/SSD

[Attached Files]

[Rev. Memo] added additional color workgroup models-IRL

[Problem code1] Other

[Problem code2] Z01: Other symptom

[Info. Type1] Other

[Info. Type2]

[Info. Type3]

[Info. Type4]

[\[OS\]](#)
[\[Emulation\]](#)
[\[Application\]](#)
[\[Network\]](#)
[\[Feature\]](#)
[\[Location\]](#)
[\[Others\]](#)
[\[Related Info.\]](#)

[\[Rating Score\]](#)
[\[Quality Score\]](#)

Please rate this TAD for future quality improvement.

Was this solution helpful?

Yes

No

I don't know

Was this TAD easy to understand?

Yes

No

I don't know